Uniform Mitigation Verification Inspection Form Maintain a copy of this form with the insurance policy

Inspection Date:							
Owner Information							
Owner Name: BROADWAY PRO	MENADE	Contact Person: BONNIE WIEDEMAN					
Address: 1268 11th Stree		Home Phone:					
City: SARASOTA	Zip: 34236	Work Phone: 941 -951-0260					
County: SARASOTA		Cell Phone:					
Insurance Company: CITIZENS	PROPERTY INSURANCE	Policy#: 1440929					
Year of Home: 2007	# of Stories: 4	Email: bwiedeman @					
I, (print name of the individual who actually performed the inspection), a personally conducted the inspection of the residence identified on this form and in my professional opinion, all the data I reported is true and correct.							
1. Building Code: What building code was used to design and build the structure? □ A. 1994 South Florida Building Code (building permit application date of 9/1/1994 or later in Miami-Dade and Broward Counties (also known as the High Velocity Hurricane Zone (HVHZ)). □ B. Building code prior to the 1994 South Florida Building Code (building permit application date of 8/31/1994 or earlier in Miami-Dade and Broward Counties (HVHZ). □ C. 2001 Florida Building Code (building permit application date of 3/1/2002 or later outside the HVHZ). □ D. Building code prior to the 2001 Florida Building Code (building permit application date of 2/28/2002 or earlier outside the HVHZ). □ E. Unknown or undetermined. 2. Predominant Roof Covering: Permit Application Date: or Date of Installation: 4 2 ∞ 7 □ A. At a minimum meets the 2001 Florida Building Code or the 1994 South Florida Building Code and has a Miami-Dade NOA or FBC 2001 Product Approval listing demonstrating compliance with ASTM D 3161 (enhanced for 110MPH) OR ASTM D 7158 (F, G or H), OR FBC TAS 100-95 and TAS 107-95, OR FMRC 4470 and/or 4471 (for metal roofs). □ B. Does not meet the above minimum requirements. □ C. Unknown or undetermined.							
3. Roof Deck Attachment: What is the weakest form of roof deck attachment? A. Plywood/Oriented strand board (OSB) roof sheathing attached to the roof truss/rafter (spaced a maximum of 24" o.c.) by staples or 6d nails spaced at 6" along the edge and 12" in the fieldOR- Batten decking supporting wood shakes or wood shinglesOR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that has an equivalent mean uplift resistance of 55 psf. B. Plywood/OSB roof sheathing with a minimum thickness of 7/16" attached to the roof truss/rafter (spaced a maximum of 24" o.c.) by 8d common nails spaced 6" along the edge and 12" in the fieldOR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that has an equivalent mean uplift resistance of 103 psf. C. Plywood/OSB roof sheathing with a minimum thickness of 7/16" attached to the roof truss/rafter (spaced a maximum of 24" o.c.) by 8d common nails spaced 6" along the edge and 6" in the fieldOR- Dimensional lumber/Tongue & Groove decking with a minimum of 2 nails per boardOR- Any system of screws, nails, adhesives, other deck fastening system or truss/rafter spacing that has an equivalent mean uplift resistance of 182 psf. D. Reinforced Concrete Roof Deck. Inspectors Initials Property Address 1268 11±6 5T. SARASOTA *This verification form is valid up to five (5) years provided no material changes have been made to the structure.							
*This verification form is valid up to five (\$\footnote{OIR-B1-1802} (Rev. 02/10) Adopted by Rule		been made to the structure. Page 1 of 4					

	E. Omer:				
	F. Unknown or unident	ified.			
	G. No attic access.				
4.	Roof to Wall Attachment:	What is the weakest roof to wall connected	on?		
	☐ A. Toe Nails Rafter		nails driven at an angle through the rafter/truss and attached		
			nailed to one side (or both sides in the case of a diamond top plate of the wall frame or embedded in the bond beam.		
	to the		ss with a minimum of 3 nails, wrapping over and securing nimum of 1 nail. The Strap must be attached to the top plate in at least one place.		
	and se		ter/truss with a minimum of 3 nails, wrapping over uss with a minimum of 1 nail. Each Strap must be attached in the bond beam in at least one place.		
		or bolts structurally connected or reinforce			
	☐ F. Other:	7.0000000000000000000000000000000000000			
	G. Unknown or Uniden	tified			
	H. No attic access				
5.	5. Roof Geometry: What is the roof shape(s)? (Porches or carports that are attached only to the fascia or wall of the host structural and not structurally connected to the main roof system are not considered in the roof geometry determination.)				
	A. Hip Roof	Hip roof with no other roof shapes grea	ter than 10% of the total building perimeter.		
	☐ B. Non-Hip Roof	Any other roof shape or combination of other roof shapes not including flat roof	roof shapes including hip, gable, gambrel, mansard and s.		
	☐ C. Flat Roof	Flat roof shape greater than 100 square	feet or 10% of the entire roof, whichever is greater.		
6.	Cable End Bracing: For roo	of structures that contain gables, please che	ock the weakest that anniv		
٠.	 Gable End Bracing: For roof structures that contain gables, please check the weakest that apply: A. Gable End(s) are braced at a minimum in accordance with the 2001 Florida Building Code. 				
		ove minimum requirements.	Joor Florida Danding Code.		
	C. Not applicable, unkr	-			
7.					
7.		· -	it wans of the structure and percentages for each:		
	☐ A. Wood Frame	%			
	B. Un-Reinforced Maso	* ———			
	C. Reinforced Masonry	<u>80</u> %			
	D. Poured Concrete	20 %			
	E. Other:	%			
8.	8. Secondary Water Resistance (SWR): (standard underlayments or hot mopped felts are not SWR) \[\begin{align*} \text{ A. SWR} \\ Self adhering polymer modified bitumen roofing underlayment applied directly to the sheathing or foam adhesive SWR barrier (not foamed on insulation) applied as a secondary means to protect the dwelling from water intrusion.				
	☐ B. No SWR				
	C. Unknown or undeterm	nined.			
9.	9. Opening Protection: What is the weakest form of wind borne debris protection installed on the structure? (Exterior openings include, but are not limited to: windows, doors, garage doors, skylights, etc. Product approval may be required for opening protection devices without proper rating identification.)				
	resistant coverings, impac	ct resistant doors and/or impact resistant w	enings are fully protected at a minimum with impact indow units that are listed as wind borne debris protection ami-Dade County and meet the requirements of one of		
Insj	A (rty Address 1268 11±4 ST.			
			changes have been made to the structure.		
	R-B1-1802 (Rev. 02/10) Adop		Page 2 of 4		

	or FBC Approval marked "For Use in the HVHZ".			
	☐ Miami-Dade County Notice of Acceptance (NOA) 201, 202 and 203. (Large Missile - 9 lb.)			
	Florida Building Code Testing Application Standard (TAS) 201, 202 and 203. (Large Missile – 9 lb.)			
	American Society for Testing and Materials (ASTM) E 1886 and ASTM E 1996. (Large Missile – 9 lb.)			
	Southern Standards Technical Document (SSTD) 12. (Large Missile – 9 lb.)			
	For Skylights Only: ASTM E 1886/E 1996. (Large Missile - 4.5 lb.)			
	For Garage Doors Only: ANSI/DASMA 115. (Large Missile – 9 lb.)			
	B. <u>All exterior openings</u> are fully protected at a minimum with impact resistant coverings, impact resistant doors and/or impact resistant window units that are listed as windborne debris protection devices in the product approval system of the State of Florida or Miami-Dade County and meet the requirements of one of the following for "Cyclic Pressure and Large Missile Impact":			
	☐ ASTM E 1886 and ASTM E 1996. (Large Missile − 4.5 lb.)			
	SSTD 12. (Large Missile – 4 lb. to 8 lb.)			
	☐ For Skylights Only: ASTM E 1886/E 1996. (Large Missile - 2 to 4.5 lb.)			
	☐ Miami-Dade County NOA 201, 202 <u>and</u> 203. (Small Missile – 2grams)			
	☐ Florida Building Code TAS 201, 202 <u>and</u> 203. (Small Missile – 2 grams)			
	☐ ASTM E 1886 <u>and ASTM E 1996.</u> (Small Missile − 2 grams)			
	☐ SSTD 12. (Small Missile – 2 grams)			
	D. <u>All exterior openings</u> are fully protected with windborne debris protection devices that cannot be indentified as Miami-Dade or Florida Building Code (FBC) product approved. This does not include plywood/OSB or plywood alternatives (see Answer "H").			
All	Glazed Exterior Openings			
	$^{\prime}$ E. All glazed exterior openings are fully protected at a minimum with impact resistant coverings and/or impact resistant window units that meet the requirements of one of the standards listed in Answer "A" of this question. (Large Missile -9 lb.)			
	F. All glazed exterior openings are fully protected at a minimum with impact resistant coverings and/or impact resistant window units that meet the requirements of one of the standards listed in Answer "B" of this question. (Large Missile – 2 lb 8 lb.)			
	G. All glazed exterior openings are fully protected at a minimum with impact resistant coverings and/or impact resistant window units that meet the requirements of one of the standards listed in Answer "C" of this question. (Small Missile – 2 grams)			
	H. <u>All glazed exterior openings</u> are covered with plywood/OSB meeting the requirements of Section 1609 and Table 1609.1.4 of the 2004 FBC (with 2006 supplements).			
	I. <u>All glazed exterior openings</u> are fully protected with wind-borne debris protection devices that cannot be identified as Miami-Dade or FBC product approved. This does not include plywood/OSB or other plywood alternatives that do not meet Answer H (see Answer "K").			
No	one or Some Glazed Openings			
	J. At least one glazed exterior opening does not have wind-borne debris protection.			
	K. No glazed exterior openings have wind-borne debris protection. This includes plywood/OSB or plywood alternative systems that do not meet Answer "H".			
	L. Unknown or undetermined.			

Inspectors Initials JKD Property Address 1268 11th ST. SARASOTA

MITIGATION INSPECTIONS MUST BE CERTIFIED BY A QUALIFIED INSPECTOR. Section 627.711(2), Florida Statutes, provides a listing of individuals who may sign this form.						
Qualified Inspector Name:						
JONATHAN KEITH GIPE	BN	INSP. License # or MSFH certificate #:				
Inspection Company:		Phone: (941) 727-2600				
DELTA ENGINEERING & INSPECTION	INC	(941) 727-2600				
Qualified Inspector – I hold an active license or co	ertificate as a: (check o	ne)				
☐ Hurricane mitigation inspector certified by the My Safe Flo	orida Home Program.					
Building code inspector certified under Section 468.607, F	lorida Statutes.					
\square General, building or residential contractor licensed under S	ection 489.111, Florida Statu	ites.				
☐ Professional architect licensed under Section 481.213, Florida Statutes.						
☐ Professional engineer licensed under Section 471.015, Flor	Professional engineer licensed under Section 471.015, Florida Statutes.					
Other individual or entity recognized by the insurer as possessing the necessary qualifications to properly complete this form pursuant to Section 627.711(2)(f), Florida Statutes.						
Individuals signing this form must have their license	or certificate in an "Acti	ve" status at time of the inspection				
		-				
I, J. KEITH GIPE am a qualified inspec	tor and I personally perf	ormed the inspection or had				
ny employee () perform the i	nspection and I agree to	be responsible for his/her work.				
Qualified Inspector Signature: Date: 4/27/2010						
An individual or entity who knowingly provides or utters a 1						
obtain or receive a discount on an insurance premium to wh						
of the first degree (Section 627.711(3), Florida Statutes). The Qualified Inspector who certifies this form is strictly liable for all						
acts, statements, concealment of facts, omissions, and documentation provided by his or her employee who actually performed the inspection.						
по поросного						
Homeowner to complete: I certify that the named Qualified Inspector or his or her employee did perform						
an inspection of the residence identified on this form and that proof of identification was provided to me or my						
Authorized Representative.						
Charles I day I to to						
Signature: Bulledeman LCAM Date: 4-28-10						
An individual or entity who knowingly provides or utters a false or fraudulent mitigation verification form with the intent to obtain or receive a discount on an insurance premium to which the individual or entity is not entitled commits a misdemeanor						
of the first degree. (Section 627.711(3), Florida Statutes)	on the individual or clienty	s not chemica commits a misuemeanor				

The definitions on this form are for inspection purposes only and cannot be used to certify any product or construction feature as offering protection from hurricanes.


Inspectors Initials AMP Property Address 1268 11th Street, SARASOTA

*This verification form is valid up to five (5) years provided no material changes have been made to the structure.

OIR-B1-1802 (Rev. 02/10) Adopted by Rule 69O-170.0155

Page 4 of 4







PRODUCT CONTROL DIVISION
BUILDING CODE COMPLIANCE OFFICE 8-25-00 FRANCISCO HERNANDEZ FL PE# 51393

EXPIRATION BATE APILL 24 2067 ACCEPTANCE NO 2-021 207 PRODUCT RENEWED

24 1/2* 1/6 3/100

74.1/4

O

827

...87.5

60.7 91.2 60.7

91.2 71.5

91.2

98.0 122.5 91.2

91.2

98.0

122.5

98.0 184.8

FALSE MUNTINS (SURFACE APPLIED) MAY BE USED

71.5 83.3 83.3

71.5 71.5 93.3 93.3

51.4 | 60.7 | 71.5

A MASD OH MIL-18175 DNID 7-12-94
TOS SIZE- AS 1/A" X AS" (1 OFER 1)
TOS SIZE- AS 1/A" X AS" (1 OFER 1)
TOSOR LOAGE- 1/50,0 -25
TOSOR LOAGE- 1/50,0 -25
MIZE MELLIANDM TEST- 1/17 PSF
TISTED CLASS- 3/14" AMPOUND

12.70

26 1/2"

37

u N

ហ

1.1 80.7 60.7

£1.3

45.7

46.7

70.0

70.0

70.0

74.9 74.9 74.8

74.9

98.0 98.0 184.B

104.0

67.5

119.2 98.0 119.2

98.0 80.0

122.5

98.0

119.2 98.0 122.5

61.5

60.7

89,5

89.6

89.6 98.0 1111.6 89.6 89.6

98.0

67.5

50.7

111.9 98.0 111.9 98.0 122.5

8

18 1% 20 1/6 28 1/2

¥

Ü N

60,7 52.6

60.7

94.7

98.0 98.0 119.1

99.2 98.0 122.5

98.0

99.2

98.0

98.0

122.5

60.7

60.7 60.7

119.1 122,5

50.7 50.7 60.7

67.5

98.0

122.5 98.0 122.5 98.0

122.5 98.0

54.8

60.7

84.8

90.5 90.6 97.1 97.1

67.5 67.5 67.5 67.5 67.5 | 60.7 |

60.7

108.8 98.0 120.3 98.0

122.5 122.5

98.0 90,6

120.3

90.6

96.0 98,0

60.7

67.5

60.7 53.2

122.5

98.0

122.5

98.0

122.5 88.0 122.5

98.0

95.5

98.0

111.9

98.0

53.2

79.8

79.8

79.8 79.8 83.8 83.8

52 **6** 67.5 67.5

80%

10 1/6 <u>در</u> ا 26 1/2" 18 1/8 8/1 DS

5

W N

S

60.7

60.7

122.5 98.0

122.5

98,0

98.0

60.7 60.7 50.7 60.7

60.7 60.7

122.5 88.7

98.0

122.5 98.0 122.5 98.0

122.5 9B.0 113,1

98.0 113,1

0.86 98.0

122,5

96.0 98.0

122.5

% 3/s

26 1/2* 16 1/8

37

4 Ġ N N

ĸ

67.5 60.7

122.5 98.0 122.5

122.5 98.0 122.5 98.0 122.5 98.0 122.5 96.0

67.5

80.7 122.5 98.0 122.5 98.0 122.5

EXT. NT.

EXT.

Ñ.

98.0 122,5 2

WIDTH HEIGHT

AND SELL

DWY! NO.

2 60.7

INT. | EXT. | INT.

NOISNEEMED

ANCHOR SCHEDULE

ALMO LHOFT

SNOOMY ... SUE

SYRO GETYBOAY 91/2

WEDIUM DUIY

SERIES-2000 ALUMINUM SINGLE HUNG WINDOW

DESIGN PRESSURE CHART - PSF

HURRICANB PROTECTION IS REQUIRED

98.0 140.8 PROBLET CONTROL DIVISION

PROBLET CONTROL DI APPROVED AS COMPLYING WITH THE

DSB-ANN, CLASS SIG" ANN, CLASS SIG" TAPOONS | 14" TAPOONS | 316" TAPOONS | 14" TAPOONS 98.0 119.1 98.0 122.5 3/16"-ANNEALED GLASS (W/STEEL REINFORCEMENT) 122.5 98.0 122.5 98.0 122.5 98.0 122.5 98.0 184.8 INT. EXT. INT. ALING AAYEH 98.0 | 122.5 | 98.0 | 184.8 98.0 122.5 98.0 184.8 122.5 111.6 122.5 122,5 122.5 95.5 122.5 98.0 144.3 122.5 98.0 184.8 122.5 98.0 122.5 98.0 184.8 98.0 98.0 184.8 0.80 98.0 184.8 98.0 98.0 98.0 ΞX I'M ANN GLASS IM" TAPCONS 168.3 118.5 184.8 184.8 184.6 184.8 184.6 Z, WINDOW HEIGHT JAMB ANCHORS SEE CHART 6" MAX. MAX TYPICAL ELEVATION 1 OVER 1 *********** HEAD ANCHORS SEE CHART (Ω) (\mathbf{w}) ANCHORS SEE CHART HTGIW WOONIN 24" MAX. 21 MAX οĵ (\bigcirc) KAX.

SHEET 1 OF 5 SH98-04 Scoin: 1/2***1' Dam Br. JN Revision 3 - 25 - 00 Derie: 3-25-99

SERIES 2000 ALUMINUM SINGLE HUNG WINDOW



FRANCISCO HERNANDEZ P. R.
Structurol Engineering
351 NW 82nd AVE #1118
Maint, Rovide 33126
Phone (305) 266 8670
Fox (305) 266 3427

1745 W. 33rd Place Halech, Parkly 33012 Ph; (305)364-9852 Fax:(305)828-5116 Monufactions, inc. Sunshine Windows

S-25-00 FRANCISCO HERNANDEZ FL PEZ 51393

ACCEPTANCE No. 0 7 -0 211.62 EXPIRATION DATE PORTIL 22 PRODUCT CONTROL DIVISION
BUILDING CODE COMPLIANCE OFFICE 8

SOUTH FLORIDA BUILDING CODE

DATE STATES OF COLUMN CODE

ET MINISTER OF CODE


TO THE CODE OF CODE

TO THE CODE

TO APPROVED AS COMPLYING WITH THE

PRODUCT RENEWED

TYPICAL ELEVATION 1 OVER 1 FALSE MUNTINS (SURFACE APPLIED)



HEAD ANCHORS SEE CHART

28 1/2* 19 1/0 8 1/8 26 1/2 16.17 53 1/1. 28 1/2 11/1/11 E3 1/8° 28 1/2 ** :/ 22 1/6 19 1/2 DIMENSION 7 26 1/2 7 47 жотн (нект ř 38 3/8 50 0/0 ξ ζ. 26 AND SILL SERIES-2000 ALUMINUM SINGLE HUNG WINDOW Ś N ü Ν. ANCHOR SCHEDULE TER JAMB DESIGN PRESSURE CHART - PSF O (n Ć 66.7 66.7 EXT. INT. EXT. INT. 56.7 66.7 66.7 66.7 | 143.0 | 66.7 56.7 66,7 65.7 66.7 148.9 66.7 300.0 66.7 66.7 | 129.3 | 68.7 | 188.9 66.7 113.1 66.7 154.0 SIG TAPCONS | 14" TAPCONS | 3/16" TAPCONS | 1/4" TAPCONS 1/4" TEMPERED GLASS
FOR LIGHT, MEDIUM AND HEAVY DUTY WINDOWS 66,7 86.7 141.8 66.7 66.7 252.1 66.7 66.7 | 281,4 | 66.7 BASED ON FIL-1837 DATED 11-18-97
TEST SIZE= 53 1/8* X 74 1/4* (1 OVER 1)
TEST LOADS= +12.5 -12.5 est
DESIGN LOADS= +12.0 -75.0 PSF
WATER INFLITATION TEST= 10.0 PSF WITH STD. SILL
TESTED GLASS= 1/4* TEMPERED 109.5 107.5 STANDARD SILL 69.8 n6.7 75.0 69.8 ba.8 B. 5. 81.0 66.7 134.2 66.7 300.0 75.0 173.2 187.7 83.8 124.0 | 86.7 | 164.4 177.2 90.6 | 66.7 | 112.4 | 75.0 | 90.6 214.0 | 66.7 | 300.0 | 75.0 HURRICANE PROTECTION IS REQUIRED 66.7 66.7 56.7 56.7 86.7 66.7 66.7 155,0 251.6 75.0 108.5 75.0 300.0 75.0 143.0 81.0 155.4 300.0 300,0 300.0 246.6 92.3 300.0 300.0 75.0 85.8 75.0 155.0 75.0 75.0 107.5 75.0 75.0 75.0 75.0 75.0 | 187.7 | 75.0 | 300.0 75.0 129.3 75.0 124.0 75.0 75.0 75.0 | 252.1 | 75.0 | 300.0 75.0 75.0 141.8 75.0 245.6 EXT. INT. 81.0 134.2 173.2 148,9 214.0 75.0 300.0 113.1 83.8 75.0 92.3 177.2 281.4 75.0 3" HIGH SILL 75,0 75.0 75,0 75.0 75.0 75.0 1112.4 75.0 75.0 | 300.0 75.0 | 300.0 75.0 75.0 188.9 2 251.6 300.0 155.4 300.0 164.4 300.0 81.0 154.0 300.0

PRODUCT CONTROL DIVISION
BUILDING CODE COMPLIANCE OFFICE
ACCEPTANCE NO. 02-0403.07

SHEET 2 OF 5 SH98-04 Dota: 3-25-99 Revision:3-25-00 Seale: 1/2"=1" Drawn By: JN

SERIES 2000 ALUMINUM SINGLE HUNG WINDOW



FRANCISCO HERNANDEZ P. B.
Structural Engineering
351 NW 82nd AVE §1118
Moni, Paride 31726
Phone (305) 256 8670
Fax (305) 266 3427

1745 W. 33rd Flood Hishan, Florido 33012 Ph.: (305)364-8952 Fax:(305)828-5118 Sunshine Windows Wanuracturing, Inc.

